



Photo 1. Walker Mine tailings near WM-7b, looking upgradient at the Dolly Creek diversion channel showing wind born tailings.



Photo 4. Photo taken approximately 100 yards downgradient of WM-7a. Showing wind born tailings over the Dolly Creek diversion channel.



Photo 2. Close-up picture of prior photo.



Photo 5. Close-up picture of prior photo.



Photo 3. Near WM-7a looking downgradient toward the Walker Mine tailings. Dolly Creek diversion structure in the foreground. Wind born tailings in the background.



Photo 6. Walker Mine Tailings, USFS Dam (WM-6). Showing water from the old Dolly Creek channel spilling over the USFS Dam.