



EXPLANATION

- C-1 Δ Surface water monitoring location
- HP-1 \odot Piezometer
- HMW-3 \bullet Groundwater monitoring well
- SUMP A-1 \square Slurry wall sump
- TRAP B \bullet Leachate monitoring location
- - - - - Approximate limit of refuse
- (1816) Groundwater elevation (FL-MSL) measured July 26, 2005
- (N/M) Not monitored
- 1820 Groundwater elevation contour (FL-MSL)
- Not used in contouring

Drawing Reference:
 Golder and Associates
 Third Quarter 2005 Monitoring Report

SITE PLAN
 RED HILL LANDFILL
 CALAVERAS COUNTY