RECOLOGY HAY ROAD

First Semi-annual 2014 Monitoring Report, Solano County, California

Submitted To: Recology Hay Road
6426 Hay Road
Vacaville, CA 95687

Submitted By: Golder Associates Inc.
425 Lakeside Drive
Sunnyvale, CA 94085

Distribution:
(1) Copy – Mary Boyd, RWQCB Central Valley Region
(1) Copy – Bryan Clarkson, Recology Environmental Solutions
(1) Copy – Amy Dietz, Recology
(1) Copy – Greg Pryor, Recology Hay Road
(1) Copy – Marcy Hannum, Solano County
(1) Copy – Golder Associates Inc.

July 30, 2014 **Project No. 053-7444-14**

A world of capabilities delivered locally

Golder Associates



LEGEND

- Groundwater Monitor Well
- Piezometer
- Landfill Gas Extraction/Leachate Well
- Leak Detection Sump
- Leachate Sump
- Lysimeter
- Gas Extraction Well
- Compliance Gas Probe
- Surface Water Sample Location
- Pond
- Groundwater Extraction Trench
- Disposal Module
- Perimeter Slurry Wall
- Groundwater Elevation Contour (ft amsl)
- Ground surface topography (2014)

500 0 500 Feet

NOTES AND REFERENCES

1) Groundwater elevations shown as feet above mean sea level.
2) Deep wells (D-) not included in contouring.
3) Site topography February 2014
4) Coordinate System: NAD 1983 StatePlane California II FIPS 0402 Feet

PROJECT
RECOLOGY HAY ROAD
GROUNDWATER MONITORING
SOLANO COUNTY, CALIFORNIA

TITLE
GROUNDWATER ELEVATION CONTOURS MAY 2014

Golder Associates

PROJECT No.		053-7444-14	FILE No.	HayRd_GWE_2014Q2.mxd
DESIGN	MM	7/26/2012	SCALE: AS SHOWN	REV. 0
GIS	DM	7/29/2014		
CHECK	KJ	7/29/2014		
REVIEW	KJ	7/29/2014		

FIGURE 3

Map Document: G:\GIS\Sites\Recology_HayRd\Maps\GWE_ContourMaps\HayRd_GWE_2014Q2.mxd / Modified 7/29/2014 11:17:13 AM by DMason / Exported 7/29/2014 11:17:35 AM by DMason